



Installation Instructions
Solder Adaptor for TIS (E) - Valves

Einbauanleitung
Lötadapter für TIS (E) – Ventile

Installatievoorschrift
Soldeeradapter voor TIS(E) - ventilen

Instructions d'installation
Adaptateur à braser pour vannes TIS (E)


Istruzioni per l'installazione
Adattatore a saldare per valvole TIS (E)

Instrucciones de Instalacion
Adaptadora para soldar válvula TIS (E)


ALCO CONTROLS

Emerson Electric GmbH & Co.
Heerstr.111 - D-71332 Waiblingen
Tel.: +49(0)7151 509-0 - Fax.: -200


1




2



3



4



T11EZ050000 PCN 861 474 05/01




Installation Instructions
Solder Adaptor for TIS (E) - Valves


Einbauanleitung
Lötadapter für TIS (E) – Ventile

Installatievoorschrift
Soldeeradapter voor TIS(E) - ventilen

1



2



Instructions d'installation

Adaptateur à braser pour vannes TIS (E)

Istruzioni per l'installazione

Adattatore a saldare per valvole TIS (E)


Instrucciones de Instalacion

Adaptadora para soldar válvula TIS (E)


ALCO CONTROLS

Emerson Electric GmbH & Co.
Heerstr.111 - D-71332 Waiblingen
Tel.: +49(0)7151 509-0 - Fax.: -200

3



4



T11EZ050000 PCN 861 474 05/01